



REPLACEMENT PART INSTRUCTIONS

EQ SYSTEMS
TIMING SHAFT SLIDE INNER TUBES
(SUPPORT ARMS)

Effective March 2024

RPI -Timing Shaft Slide Inner Tubes



(800) 846-9659

EQ SYSTEMS TIMING SHAFT SLIDE INNER TUBES (SUPPORT ARMS)

March 2024

The below only applies to the EQ Systems internal gear/Rack slide assemblies.

Inner Tube Assembly (support arms) includes internal gear rack

Gulf Stream, Conquest, Endura, Sundowner, Pace Optima and Forest River Diesel coaches.

Left Hand Tube #1728L | Right Hand Tube #1728R

Above slides, except for 42-inch travel #7089 used on Gulfstream/Conquest, are considered obsolete. Tubes #1538L and #1538R with gear rack #1279 would be a special build with long lead time. No inventory of tube/rack parts. These tube parts are not listed in the current inventory lists.

**Tube support buttons. Multiples needed for each Tube assembly.
The exact number of each and which ones are needed varies,
somewhat depending on the specific slide.**

Large 1.5" #1392 | Medium ¾" #1752 | Small ½" #1725

Inner tubes manufactured after 2006 use (2) 1 ½" buttons #1392 top and bottom and (2) ¾" on sides. Prior tubes vary on needed buttons.

Note: if you are not clear on this process please call EQ Systems for assistance.